

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 11/02/2023 @ 11:57 AM
Model Year: 2013 Vehicle Make: GMC
VIN (manually entered or from DMV document): 1GKRE5FCE19151
License Plate: 6WY8C97 License State: CA
Certification Type: California Odometer: 143845
Fuel Type: Flexible fuel
GVWR: 4,805 - 10,000

Overall Test Result:

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well-maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: TXM5X2BC
DMV ID Number: 545XX122103

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance. Please keep this copy for your records.

The Bureau of Automotive Repair helps consumers with Smog Check repairs, vehicle retesting, collision repair inspections, and more.
www.bar.ca.gov

Visual Inspection Result Information

Result	Inspection Category	Result	Inspection Category
NOT APPLICABLE	Air Injection System	PASS	Catalytic
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crackdown Emission Controls
NOT APPLICABLE	Emissions Gas Recirculation (EGR)	PASS	Fuel Evaporation System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOT APPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines or Sensors/Switches

Emissions Control Systems Functional Check Results

Result	Test	Result
PASS	Liquid Fuel Leak Check	PASS
PASS	Smoke Check	OBDII

Smog Check Inspection Station Information

Station ID: TC267198
ORINDA TEST ONLY SMOG STATION
22 HEYANT WAY
ORINDA, CA 94563
(925)254-2817

Inspector Name/ID:
Software Version/OIS ID:

WONG, JERRY/01047838
23.1.1983.0/CV011255

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all laws, requirements, and that the information listed on this vehicle's inspection report is true and accurate.

11-2-23

Inspector's Signature

Date